SEE R.O.S. 5-52 AND 13-21

Bonnefoy

(RECORD S. 00°05'E. 2594.42 5-M-52)

N. 00°03'25" W. 2593.70'

1/4 Section Line

1296.85

881.43'

112.69

302.73'

Found 3/4" Hex Drill Steel in mound of rocks at North 1/4 Corner of Section 22 - as per 5-M&P-52

1/16 Corner

Found 1/2" steel rod tagged L.S.2902 - Co. Surveyor - 10.5711

462.08'

N. 77°06'50" E. 454.54'

437.14'

N. 77°06'50" E.

Found 1" pipe in rock mound at the Center of Section 22 as per 5-M&P-52

3.657 Ac.

(R) N. 2°56.20" W.

935.89'

2637.20'

L=1220.47'

R=5593.58'

L=714.51'

(R) S 25°50.33" E.

(R) S 23°28.1" E.

(R) S 33°27.9" E.

(R) S 35°07.53" E.

225.97'

510.91'

R=2737.60'

0.177 Ac.

56.74'

N. 89°41'07" W.

101.17'

133.68'

1/16 Cor

1/16 Section Line

2639.39'

F. Boskovich 48-OR-417

71.547 Ac.

N. 00°18'53" E.

1600.34'

1835.14'

1/16 Section Line

(R) S 40°28.1'0" E.

(R) N. 40°25.38" W.

R=2824.7'

R=1540'

STATE HIGHWAY "88"

L=571.21'

Δ=21°15'07"

L=612.01'

Δ=21°15'07"

(R) S 6°40.45" E.

N. 61°50'40" W. 9.96'

N. 28°32'1" E. 325.13'

N. 28°32'1" E. 325.13'

(STATE HIGHWAY BOOK 2 - PAGE 61)

R=2050'

R=1950'

Δ=23°50'50"

Δ=22°20'50"

L=853.24'

L=811.61'

S. 52°06'52" W. 69.1'

S 62°06'52" W 26.80

126.84'

35.575 Ac.

N. 57°03'40" E. 65.57'

N. 66°07'10" E. 148.46'

N. 72°33'40" E. 56.09'

N. 88°58'20" E. 72.20'

N. 87°27'00" E. 27.81

N. 78°44'30" E. 54.64

N. 71°12'10" E. 59.25'

N. 76°49'10" E. 55.35'

N. 52°14'00" E. 129.37

ROTATED 0°29'20" COUNTER-CLOCKWISE FROM RECORD

Fence Line

N. 38°07'50" E. 181.38'

N. 39°41'20" E. 87.98'

N. 46°54'10" E. 19.41'

N. 50°15'50" E. 38.30'

N. 46°37'20" E. 188.90'

N. 52°34' E. 42.08'

N. 38°38'30" E. 183.57'

N. 51°30'30" E. 189.52'

SEE R.O.S. 7-62

Mark Eudey 15-OR-90

SEE R.O.S. 14-10

Found 1" iron rod in mound of rocks as per 14-M&P-10.

1279.50'

1279.50'

S. 00°10'42" E.

2559.00'

S. 88°33'43" E.

S. 88°11'01" E.

1318.60'

1/16 Cor

1/4 Section Line

Section Line

1717.05'

S. 00° 07'47" W.

(Record N.0°26'20"E 8-M&P-71)

2615.95'

772.06'

Found 2"x3" iron bar marked "Sec. Cor. C.B.11" See 8-M&P-71 and 7-M&P-62

W. 1/4 Corner of Section 22 Found 24" bull pine with evidence that the fence went West from here - A 3/4" steel rod tagged R.C.E.5702 bears N.0°10'42"W. 2.00'

F. Boskovich 48-D-414 48-D-394 19-D-18

Roman Catholic Bishop of Sacramento 146-OR-110 SEE R.O.S. 8-71

SEE R.O.S. 7-62 St. Sava Church 115-OR-553

15 22 21 16

22 27 28

## SURVEYOR

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyor's Act at the request of Terry Freshour in June, 1968.

V. J. Gretzinger R.C.E. 10761

## COUNTY SURVEYOR

This map has been examined for conformance with the requirements of the Land Surveyor's Act this 26th day of June 1968.

Ledger L. McMinn
Amador County Surveyor

## COUNTY RECORDER

Filed this 18th day of JULY 1968 at 9:55 A.M. in Book 14 of Maps and Plats at page 36, at the request of Ledger McMinn, Amador County Surveyor

Fee $5.00

Amador County Recorder

Matthew Bachich 68-OR-337

# RECORD OF SURVEY

## PORTION OF THE WEST 1/2 OF SECTION 22, T.6N., R.11E., M.D.M., AMADOR COUNTY CALIFORNIA

SCALE 1" = 200' JUNE 1968

V. J. Gretzinger
Civil Engineer
Jackson, Calif.

## NOTES AND LEGEND

—⊙— Denotes 3/4" steel reinforcing rod tagged R.C.E. 10761, and set on this survey.

—○— Denotes found 6"x6" concrete highway monument.

—•— Denotes found 3/4" rod tagged L.S. 2720

The meridian of this survey is based on solar observations in the field.